Weathertzenton Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-1298/1

Work Order Type: Weatherization

Audit Name: 17017UC-1298

CLIENT INFORMATION

Client ID: 17017UC-1298

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Fax:

Address: 3313 Williams Enterprise Drive

Cookeville, TN 38506 Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1983 MOBILE HOME

Client ID: 17017UC-1298

Measures

Client ID: 17017UC-1298

	Measure 1 Seal Ducts			Components					Inspected	
C		pair duct registers with ma pair ducts X 2	stic X13							
					Estimated	Estimated Act				
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	Duct sealing (setup cost)	Each	1						
10	Miscellaneous Supplies	Duct Sealing	Each	1						
C	Other Detail									
				Measur	e Sub Total:		Sub Total:			
	<i>Measure</i> 2 Gen	eral Air Sealing terior exterior windows x	14		Componen				Inspected	
C	Comment Caulk in	terior exterior windows x			Estimated			Actual		
<i>C</i>	Comment Caulk in	terior exterior windows x	Units	Qty	-		Qty		Inspected Total	
<i>C</i>	Comment Caulk in	terior exterior windows x		Qty 1	Estimated		Qty	Actual		
# 1	Comment Caulk in Material / Labor Insulation Miscellaneous	terior exterior windows x Description / Comment General air sealing	Units		Estimated		Qty	Actual		
# 1	Comment Caulk in Material / Labor Insulation Miscellaneous Supplies	Description / Comment General air sealing (setup cost)	<i>Units</i> Each	1	Estimated		Qty	Actual		
# 1	Comment Caulk in Material / Labor Insulation Miscellaneous	Description / Comment General air sealing (setup cost)	<i>Units</i> Each	1	Estimated		Qty	Actual		
# 1	Comment Caulk in Material / Labor Insulation Miscellaneous Supplies	Description / Comment General air sealing (setup cost)	<i>Units</i> Each	1	Estimated		Qty	Actual		
# 1	Comment Caulk in Material / Labor Insulation Miscellaneous Supplies	Description / Comment General air sealing (setup cost)	Units Each Each	1	Estimated			Actual		

Measure 3 DWH Tank Insulation				Componen		Inspected		
Comment								
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Tank Insulation	Each	1					
2 Labor	DWH Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Measure 4 Tur Comment	ne up heating system			Componen				Inspected
# 88-1-4-1-1/1-1	D	Hadia		Estimated			Actual	T-1-1
# Material / Labor0 Unspecified	Description / Comment Misc Material	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
·	wise waterial	Lacii	'					
Other Detail								
] [] []		
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:] ,	Sub Total:	

Report Run On: 5/24/2010

DOE Weatherization Assistant Version 8.5.0 Page 3 of 4

Measure 5 vent dryer from floor to outside			Components					Inspected
Comment to prev	ent moisture problems							
				Estimated	1	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Monte On	rdon Cro	nd Total:		Cron	d Total:	
		vvork Or	der Gra	nd Total:		Gran	d Total:	

Client ID: 17017UC-1298